

March

## ***NICs Failing DHCP on PAPT LAN***

***IEEE 48-Bit MAC  
Address (Cisco  
Format)***

***Date***

***Source Description***

---

0001.6c30.ff88	03/08/05	Enpower Sparx ENSP4 Foxconn 650/651 Board w/ onboard SIS 900 Based Ethernet
0004.764b.0497	03/09/05	Dell Inspiron 8100 w/ Integrated 3Com 3c90x WinXP
0011.09c7.f4c0	03/09/05	Via Rhinell Integrated in MSI MS-7061 / KM400 Item #A4854799
000f.ea7d.b9db	03/11/05	Gigabyte P4 Titan GA-8s661FXM-775 from RTG; SIS 900 Chipset
00e0.b83d.225c	03/15/05	Gateway Solo P4 w/ Intel 100/Pro VE Ethernet
0001.6c30.fe3f	03/16/05	Enpower Sparx ENSP4 Foxconn 650/651 Board w/ onboard SIS 900 Based Ethernet
0001.6c30.fea0	03/16/05	Enpower Sparx ENSP4 Foxconn 650/651 Board w/ onboard SIS 900 Based Ethernet
0004.75c9.b0f2	03/21/05	3Com 3c905-C TXM In Gateway Essential 550
00d0.5908.77b0	03/22/05	Acer Laptop NIC-559A Pro/100+
0010.b53f.ca79	03/24/05	HP EN1207D 10/100 PCI in HP Pavilion 8660C
0003.0d18.73d1	03/23/05	RealTek RTL8139/810x in Enpower Genie